

Maximum Number of Torch Tips (*theoretical values)								
Gauge Number Tip Size	With Booster - max. output				Without Booster - max. output			
	MG-25	MG-75	MG-150	MG-300	MG-25	MG-75	MG-150	MG-300
14				1				
15				1				
16			1	2				1
17			1	2				1
18		1	1	2			1	2
19		1	2	6			2	3
20		1	3	9			2	4
21		1	4	11			3	5
22	1	1	7	18			5	9
23	2	2	10	28		1	8	14
24	2	3	12	30	1	2	9	15
25	3	4	18	30	1	2	13	18
26	3	4	18	30	1	2	13	22
27	5	6	24	30	2	4	18	30
28	8	10	30	30	5	8	30	30
29	8	10	30	30	5	8	30	30
30	8	10	30	30	5	8	30	30